



Trail Uses



Hiking



Bicycling



Equestrian



No Motorized Vehicles



Dogs

Hazards and Obstructions



Ruts
4 in.



Rocks
6 in.

Alhambra Creek Trail

Briones

Trail Length 1.0 mi (1.5 km)

Network trail

Alhambra Creek Trail starts out gradually and then becomes fairly steep. This shady trail winds through a wooded area of Briones and makes for a beautiful and cool hike on a hot summer day.

Cumulative Gain 397 ft (121 m)
Elevation Change Loss 5 ft (2 m)



Typical Grade is 8.0%

19% of the trail is between 14% and 21%
100 ft (30 m) is between 20% and 21%
8% grade is a standard ramp.



Typical Cross Slope is 5.1%

9% of the trail is between 8% and 100%
208 ft (63 m) is between 12% and 100%



Typical Tread Width is 127 in (323 cm)

Tread Width ranges from 80 in (203 cm) to 277 in (704 cm)
Minimum Clearance 47 in (119 cm)



Trail Surface is Soil

76% of the trail is Firm or better
1198 ft (365 m) of the trail is Soft or worse

Trailhead Location

Accessible from the Alhambra Creek staging area off of Reliez Valley Road.



Trail Access Information

Warning: Trail conditions may have changed since this trail was assessed. Temporary obstructions (e.g. fallen trees or land slides) may not have been mapped. Maximum grades and cross slopes may vary.

Obstructions less than 2.0 in (5.0 cm) or outside the tread area 120 in (3 m) wide by 96 in (2.4 m) high were not measured. Minimum clearance boundaries were at least 2.0 in (5.0 cm) high.

This report has been generated by TrailWare which has been created by Beneficial Designs, Inc.

Alhambra Creek Trail

Length 1.0 mi (1.5 km)

Network trail



Hiking



Bicycling



Equestrian



Typical Grade 8.0%

19% of the trail is

14% to 21%

100 ft (30 m) is 20% to 21%
8% grade is a standard ramp.



Typical Cross Slope 5.1%

9% of the trail is

8% to 100%

208 ft (63 m) is 12% to 100%



Typical Tread Width

127 in (323 cm)

Minimum 80 in (203 cm)

Maximum 277 in (704 cm)

Minimum Clearance 47 in (119 cm)



Soil

76% is Firm or better

1198 ft (365 m) is Soft or worse



Ruts 4 in.



Rocks 6 in.



Trail Access
Information



Warning: Trail conditions may have changed since this trail was assessed. Temporary obstructions (e.g. fallen trees or landslides) may not have been mapped. Maximum grades and cross slopes may vary.

This report is generated by TrailWare which has been created by Beneficial Designs Inc.

Aug 25, 05

Alhambra Creek Trail

Briones

Trail Access Information Summary

Trail Length 1.0 mi (1.5 km)

Network trail

First Segment Assessed

page 1

Jul 11, 05

Last Segment Assessed

Jul 11, 05

Cumulative Elevation Change

Gain 397 ft (121 m)

Loss 5 ft (2 m)

Typical Grade is 8.0%

19% of the trail is between 14% and 21%

100 ft (30 m) is between 20% and 21%

8% grade is a standard ramp.

Locations and lengths can be found on the Maximum Grade Table Reports

Typical Cross Slope is 5.1%

9% of the trail is between 8% and 100%

208 ft (63 m) is between 12% and 100%

Locations and lengths can be found on the Maximum X-Slope Table Reports

Typical Tread Width is 127 in (323 cm)

Tread Width ranges from 80 in (203 cm) to 277 in (704 cm)

Minimum Clearance Width is 47 in (119 cm)

Locations and lengths can be found on the Minimum Tread Width Table and Minimum Clearance Width Reports

Trail Surface is Soil

76% of the trail is Firm or better

1198 ft (365 m) of the trail is Soft or worse

Length of trail can be found on the Surface Type Table and Surface Category Table Reports.

Obstructions

Ruts 4 in.

Rocks 6 in.

Locations and lengths can be found on the Minimum Vertical and Maximum Tread Obstructions Reports

Trail Uses

Hiking

Bicycling

Equestrian

Warning: Trail conditions may have changed since this trail was assessed. Temporary obstructions (e.g. fallen trees or land slides) may not have been mapped. Maximum grades and cross slopes may vary. Obstructions less than 2.0 in (5.0 cm) or outside of the tread area a 120 in (3 m) wide by 96 in (2.4 m) high were not measured. Minimum clearance boundaries were at least 2.0 in (5.0 cm) high.